

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic (Inland: Committee, London, Telex
Address | Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

27th April,,1966.

Dear Sirs,

C.
DD/DET

M.S. "MONSUN"

When this ship was at New York during February, the Surveyors examined the repairs in way of the port forward end of the main engine "A" frame plating at the centre of the engine in way of the chain drive casing, and whilst considered efficient meantime, it was recommended that these repairs be again examined by the end of March 1967.


The Committee have therefore continued the ship's class subject, inter alia, to this matter receiving attention by that time, and I shall be glad if you will inform the Owners accordingly.

It will also be appreciated if you will remind the Owners that the repairs to the welds of the stiffening plates between main engine frames Nos.8 and 9 forward and aft, and No.6 aft port side require to be specially examined by the end of June next.

Yours faithfully,

The Surveyors,
HELSINGFORS.

pro Classification Manager



Lloyd's Register
Foundation

013284-013292-0235