

SHIP'S NAME

MONSUN

PORT

N. YORK

No. 64750

"M"

LAST SURVEY DATE 21-2-66.

CLASS IS SUBJECT TO

- 1/ REPAIRS TO WELDS OF STIFFENING PLATES BETWEEN M/E FRAMES N^o 8 & 9 F&A & N^o 6 AFT PORT SIDE (E.W 664) BEING SPECIALLY EXAMINED BY G.66 (12ms)
- 2/ P.F END OF M/E "A" FRAME PLATING AT CENTER OF ENGINE IN WAY OF CHAIN DRIVE CASING REPAIR (9.66) BEING SPECIALLY EXAMINED BY 3.66

SUBJECT ITEM 2/ EXAMINED & SURVEYOR RECOMMENDS
RE-EXAMINATION BY 3.67.

ON ACCOUNT OF HEAVY WEATHER DAMAGE REPAIRED
EFFECTED TO DECK PIPE LINES, ELECTRICAL EQUIPMENT
ON DECK WAS TESTED WITH SATISFACTORY RESULTS

C.S. A. 1
This
is to be removed
as CLASSED. SUBJECT AS ABOVE
ITEM 1/ & ITEM 2 AMENDED TO
LIMIT DATE 3.67



© 2021

14/4/66

Lloyd's Register
Foundation