

11 8 NOV 1965

SHIP'S NAME MONSUN

Appdx-M

PORT HKG 19640
YKA No. 6188

LAST SURVEY DATE 25.9.65

CLASS IS SUBJECT TO

Repairs to welds of stiffening plates between
H/E A frames Nos. 8 & 9 fwd. & aft. & No. 6 aft
port side (EW. 6.64) being specially examined by 6.66
(12ms).

CSA completed. TS now held
SPS now held. ABS due 6.65, now commenced.

Docking Weardown 18"

Port fwd end of H/E A frame plating at centre
of engine in way of chain drive conig found with
fractured weld connection. Doubler plate welded on
& sea recommends the repairs be specially examined
before end of 3.66

It is submitted that this
vessel is eligible for THE

RECORDS CSA 9.65, TSCL 8.65 & SPS 9.65

CERTIFICATE WRITTEN.

now or ABS 9.65 when survey completed,
subject as above as recommended.

C.N.T. 17/11/65 806 → COVER.