

THROUGH HELSINGBORG.

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

2nd August, 1962.

Dear Sirs,

Motorship "MADELINE".

C.

A report of survey held by the Society's Surveyors at Singapore in June has now received the consideration of the Committee.

AG/SM

At that survey damage was reported to the main engine No.6 unit, and as repairs could not be satisfactorily completed, the No.6 unit was cut out and disconnected.

It was recommended that the main engine No.6 connecting rod, crosshead and crankpin bearings be specially examined and dealt with as necessary on the ship's arrival at a Continental or Baltic port on completion of the present voyage.

The Committee have continued the class subject to this matter receiving attention.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

Messrs. A/B Verna,
Kungsgatan 2,
HELSINGBORG,
Sweden.



© 2021

Lloyd's Register
Foundation

013284-013291-0270