

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME ^{SS} ESSO JAMAICAREPORT *Francis* No. 9910.

7/12/62

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR


In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey..... When due.....

Before this case receives consideration, the Surveyor should be informed of the condition of class namely, Centre forced-draught fan-motor controller being permanently repaired by 9/62 and extended to 12/62, and asked whether this item was dealt with.

Further, he should be asked whether the essential pumps, namely bilge, ballast and O.F. transfer pumps, in the pump room the staving-gear including the starboard pump and motor but except the Port pump and motor were examined to complete the C.S. He should also confirm that there are no separate O.F. tanks.

WAC
12/11/63



© 2021 (End under)

Lloyd's Register Foundation

013322-013328-0100