

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

27th May, 1963.

C.
DHGK/BN

Dear Sirs,

M.S. "LUGANSK"

Before your Report No. 10153 receives consideration you should confirm that the secondary safety valves of the auxiliary boilers were also adjusted under steam.

I also have to point out that the exhaust gas economiser safety valves require to be adjusted under steam to complete the Auxiliary Boiler Survey for a notation of ABS 2.63. You should therefore issue an amended Interim Certificate, and forward a copy to this Office.

Yours faithfully,

c.c. ~~File~~. Classing letter File

Clerk to the
Classification Committee.

The Surveyors,
PIRAEUS



© 2021

Lloyd's Register
Foundation

013322-013328-0153