

Ship's name

LUGANSK

Port

PIRAEUS

No.

10158

Class is subject to

NIL

Last survey date

Before this case receives consideration it is concluded that the secondary safety valves of the auxiliary boilers were also adjusted under steam, and this should be confirmed by the Piraeus Surveyors.

It will also be noted that the exhaust gas economiser safety valves have to be adjusted under steam to complete the boiler survey with date of ABS 2.63.

Amended inspection certificate to be issued accordingly.

AKS 27/5/63