

COPY

Kobe Rpt. 9

No.

11431

LLOYD'S REGISTER OF SHIPPING



BL-87324

Port KOBÉ

13th March, 1963.

This is to Certify that ~~we~~ ^{we} have surveyed part of the machinery of the m.s. "LUGANSK" 22,262 Gross tons of Odessa for part ABS and part machinery whilst the ship lay afloat and in dry dock at Aioi on the 23rd February, 1963 and subsequently

our ~~my~~ recommendations have been carried out to my satisfaction. ~~I~~ ^{we} are ~~are~~ reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned ABS 2,63 when the survey is completed.

Parts now examined:—To Complete ABS 2,63:

The safety valves on both auxiliary/primary boilers and exhaust gas economiser to be adjusted under steam.

Machinery part now examined at Owners Request:—

M.E. Nos. 1 - 9, cylinders, covers, pistons & rods.
M.E. Nos. 1 - 9, valves & gears.

Seacocks and fastenings.
Propeller.

E.G. White for P. Manson & self

K. Tabuchi

Surveyor to Lloyd's Register of Shipping
P. Manson, E.G. White & K. Tabuchi

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150°F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of the Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."