

TELEPHONE NO. 184.



Lloyd's Register of Shipping,

RECEIVED

24 AUG 1949

ANSD



~~Dock Offices,~~ Dock Chambers,

Barry, 23rd. August 1949.

Reference

S.

Dear Sir,

"BARON MACLAY" (B.C.) Barry Report 25997.

We thank you for your letter of the 19th. instant and in reply thereto have to state that in addition to propeller and sea fastenings a general examination of the main and auxiliary machinery, boilers, steering engine and windlass was made by us.

As regards Hull and Equipment the Annual Freeboard Survey was not due at this time, but the survey carried out by us was equivalent to that required for an Annual Survey except that the watertight doors were not examined or the steering gear chains annealed and tested.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS,

Per:-

The Secretary,
LONDON.

© 2021

Lloyd's Register
Foundation

013329-013338-0437

Floors

Have Watertight Doors been examined and found

Mastheads & Stemson

Transoms, Pointers & Crutches

H & F

Waley

W. J. Lufarbull.

Noted.

24
8
49

clerk carry over still to be

Annual Lead line

done J. 5/10/49



© 2021

Lloyd's Register
Foundation