

12 APR 1957

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

GB

SHIP'S NAME "BETTET" REPORT Sba. No. 6085

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

The class is subject to indented bottom shell plating etc. (p & s) being specially examined next drydocking.

A SPECIAL SURVEY (A) became due 9,56.

The Notation of "Class Suspended - Surveys Overdue" was inserted in the Register Book 19.10.56.

The SOURABAYA Surveyors report (3,57), this ship examined in dry dock, bottom coated and the requirements of a SPECIAL SURVEY (A), due 9,56, complied with.

Minor wear and tear repairs effected.

The deferred items, as above, specially examined, found to continue efficient and now recommended to be dealt with at Owners' convenience (Category B).

IT IS SUBMITTED DS 3,57 and Notation of 'ss.Sba. 3,57' be assigned, without special conditions but with Endorsement (B).

DS 3,57 } Without.  
ss.Sba. 3,57 }

ENDORSEMENT OF CERTIFICATE.

Indents in a few bottom and side shell plates (p & s).

DELETE FROM R.B.

"Class Suspended-Surveys Overdue"

*S.P.R.*  
4-4-57.

Notes  
for  
Header



© 2021

Lloyd's Register  
Foundation

013339-013345-0059