

Rpt. 8

Port Sourabaya.

No. 6085.

Date of writing Report 21-3-'57.

When handed in at Local Office

Received London

27 MAR 1957

Survey held at Sourabaya

No. of Visits 11

First Date 30 - 1 19 57.

Last Date 19 - 3 19 57.

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B.

53655

on the ~~SS~~ Steel M.S.

" B E T T E T "

Tons gross 194

Built at Sliedrecht.

By Whom N.V. Scheeps. "De Klop"

When 1952 - 9.

Owners Republik Indonesia.

Owners' address (If not already in R.B.)

Managers Djawatan Pelajaran.

Port of Registry Djakarta.

Surveyed Afloat or in Drydock Drydock

Name of Dock D.M.S.

Date of last examn. in Drydock 12-2-'57.

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 5985

Port Sba

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
+ 100A1 1/56	+ LMC N9/52M3/56 CL 1/56

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined.

Freeboard as marked on ship and now verified 3 ft 4 1/4 ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Special Survey (A) due 9.56. Ship 4 years old.

Repairs due to wear and tear: A number of rivets Port-and Starboardside shellplating renewed. Lower bush of rudder renewed. A number of minor repairs carried out.

S.R.L. Indented bottom and shellplating Port-and Starboardside specially examined and found satisfactory. With a view to the above and the intention of the Owners to deal with the indented bottom and shellplating at their earliest convenience, it has been recommended to delete same item from S.R.L. and placed in list of endorsements B of class.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes.

Is Classification Certificate required? If so, to be sent to Sourabaya Surveyor.

If so, is the Report sent now, or when will it be sent? Now.

Has Interim Certificate been issued? Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or "to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

It is submitted this ship is eligible to be continued as classed with fresh records of Special Survey 3.57 and docking 3.57 and have item "indented bottom & shellplating Port-and Starboardside" be deleted from S.R.L. and placed in list of endorsements.

Jacobs
Surveyor to Lloyd's Register of Shipping

Date of Committee

TUESDAY 16 APR 1957

Minute

SS 3.57 without opl ch

SS Sba 3.57 ES 3.57

(with endl).

Delete "Class suspended - surveys overdue"


30m. 5.56

CERTIFICATE WRITTEN.

013339-013345-0060

Noted for Header

NOTED FOR LISTING



© 2021

Lloyd's Register Foundation

