

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Steel S.S. "EUDUNDA" Rpt. Syd. No. 6732.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor.....

1st Entry

This vessel has left for Melbourne to have machinery installed, and this report should await completion report from the Melbourne Surveyor. To complete the survey, windlass & steering gear require to be tested and the chain cables verified with the certificates.

The Sydney Surveyors should be informed that in future cases particulars of the longitudinal framing etc ~~on Rpt 1*~~ as fitted ~~on~~ ship should be given in the spaces provided on Rpt 1* as well as particulars as approved.

Ans 27-1-21

M. AEB
27-1-21
© 2021
Lloyd's Register
Foundation
013346-013356-0306