


7th September, 1961.

HONG KONG

16414 - As recommended.

16421 "TEH HU" - As recommended. It is concluded that the lengths of chain cable replaced at this time have been tested in accordance with Rule requirements.



Lloyd's Register
Foundation

013376 - 013382 - 0124