

4E

The class is subject to repairs to the ~~base~~ of the main engine driven air pump being examined by 2.58 (12 months limit).

30 MAY 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... TARGET..... REPORT..... Hull No. 63965

ES due 6.58, partly held 2.57, not advanced.

MBS due 1.58, now held.

SRL: The above item dealt with.

IT IS SUBMITTED this vessel is eligible for the record of MBS 5.58 now, and ES 2.57 when the survey has been completed, without special condition.

To complete the ES:

?
See Middlesbrough Report No. 20912

22.5.58

013376- 013382- 0284

© 2021

Lloyd's Register
Foundation