

Rpt. 8

Port MIDDLESBROUGH. No. 20912.

Date of writing Report 15th Feb. 1957. When handed in at Local Office

Survey held at MIDDLESBROUGH. Received London 20 FEB 1957

No. of Visits 3 First Date 5.2. 1957 Last Date 7.2. 1957

# REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B. 79856 on the Iron or Steel ~~XX~~ S.S. "TARGET" Tons gross 201

Built at Rowhedge. By Whom Rowhedge Ironworks Co. Ltd. When 1936 Year Month

Owners Dorman Long (Chemicals) Ltd. Owners' address (If not already in R.B.)

Managers Port of Registry Middlesbrough. Surveyed Afloat or in Drydock Drydock. Name of Dock Smith's Dock. Date of last examn. in Drydock 7/2/57.

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 20878 Port Mdb. To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery
Date of Special and of Drydocking Surveys, etc.		
BS*	6/54.	MBS* 6/54.
	river Service.	BS. 1/57.
	ss.Mdb.6/54.	TS(CL) 6/54.

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined. Freeboard as marked on ship and now verified ft ins

EXAMINATION AND REPAIRS AS PER RULE FOR Docking and Annual Classification Survey.

Wear and Tear Repairs.  
Rudder set over to port in way of bottom arm released and faired.  
A number of shell rivets welded or caulked as found necessary.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes. Now. Is Classification Certificate required? If so, to be sent to No. Has Interim Certificate been issued? Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or "to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

This ship so far as now surveyed is eligible in my opinion to remain as classed. and to have record of Drydocking. 2.57

SRK.  
5-3-57.

*[Signature]*  
Surveyor to Lloyd's Register of Shipping

Date of Committee THURSDAY 14 MAR 1957  
Minute 2.57 Mdb subject M  
S 2.57

Noted or Leader

NOTED FOR POSTING



© 2021 Lloyd's Register Foundation

013376-013382-0291

