

4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

12 MAR 1957

NAME

"TARGET"

REPORT

Mdb.

No. 20912

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

LMC MS. due 6,58, partly held now.

Docking. Screwshaft seen. Some repairs now effected to the base of the main engine driven air pump, and the Surveyor recommends that these repairs be examined by 2,58.

IT IS SUBMITTED that this vessel will be eligible for the record MS. 2,57 when the Survey has been completed, TS. 2,57 now, subject as recommended.

To complete the Survey:-

See this report.

7.3.57.



© 2021

Lloyd's Register
Foundation

013376 - 013382 - 0301