

1

Sent to Chief Surveyors.....

GB

Received from Chief Surveyors.....

SHIP'S NAME "MOUNT ITHOME" REPORT N.Yk. No. 60961

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey. Fitting of thermometers in ..... When due .....  
tunnel side plating.

NOTED.

SUBJECT to openings in shaft tunnel side plating (p & s) being permanently closed on completion of discharge of present cargo at a Japanese port.

*Sa Memo 27.9.62*

IN S.R.L. APPENDIX.

Indents in shell plating etc. (p & s).



© 2021

*James*  
11/8/62  
Lloyd's Register  
Foundation

013390-013396-0018