

C  
O  
P  
Y

LLOYD'S REGISTER OF SHIPPING  
PHILADELPHIA

The Secretary  
NEW YORK

S.S. "MOUNT ITHOME"

Dear Sir:

Enclosed, herewith, is report of S.E.2 survey and Rpt. 9 of Boiler Survey of the above named vessel. On May 2nd a visit was made to the vessel to verify renewal of part chain cable and a Rpt. 8 (No.11416) was sent to your office on 4th idem. However, the vessel's schedule was changed to take a cargo of scrap iron to Japan, in consequence of which the Owners found themselves in a position to do the boiler survey at this port at a later date, which accounts for the Rpt. 9 with a different committee number, viz., 11430.

With respect to the S.E.2 survey and the safety equipment certificate which expires the 27th instl, the Owners requested a Rpt. 10 (copy enclosed) to cover the Safety Equipment Survey pending issue of a new Safety Equipment certificate.


While going through the vessel's Class and other Certificates, an expired LL.S.T. and copy, issued at Piraeus in November, 1960, was noted and is enclosed.

The report of Radiotelegraphy Survey was already forwarded to you on the 23rd instant.

Yours very truly,

EW/fas  
Encl.

For the Surveyors



© 2021

Lloyd's Register  
Foundation