





1939  
 March 9. 16. 20. 22. 31. April 6. 11. 12. 13. 19. 24. 25. 27. 29. May 3. 12. 19. 22. 23. June 2. 8.  
 14. 27. 28. 29. July 11.  
 During progress of work in shops - -  
 During erection on board vessel - - -  
 Total No. of visits 26.

Dates of Examination of principal parts—Cylinders 19. 5. 39. Slides 8. 14. / 6. 39. Covers 19. 5. 39

Pistons 8. 6. 39. Piston Rods 3. 5. 39. Connecting rods 8. 6. 39

Crank shaft 19. 4. 39. Thrust shaft Intermediate shafts

Tube shaft Screw shaft Propeller

Stern tube Engine and boiler seatings Engines holding down bolts

Completion of fitting sea connections

Completion of pumping arrangements Boilers fixed Engines tried under steam

Main boiler safety valves adjusted Thickness of adjusting washers

Crank shaft material 3/4" Identification Mark 1242/3/4/5 AEG 7. 3. 39 RM 28. 4. 39 Thrust shaft material Identification Mark

Intermediate shafts, material Identification Marks Tube shaft, material Identification Mark

Screw shaft, material Identification Mark Steam Pipes, material Test pressure Date of Test

Is an installation fitted for burning oil fuel Is the flash point of the oil to be used over 150°F.

Have the requirements of the Rules for the use of oil as fuel been complied with

Is the vessel (not being an oil tanker) fitted for carrying oil as cargo If so, have the requirements of the Rules been complied with

If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with

Is this machinery duplicate of a previous case yes except attached pumps If so, state name of vessel SS MULUBINBA NWE 94924.

General Remarks (State quality of workmanship, opinions as to class, &c. This engine has been made under special survey in accordance with the requirements of the Rules.

The materials & workmanship are good.  
 The engine has been shipped to Hong Kong for fitting on board.

Certificate to be sent to

The amount of Entry Fee ... £ 4 : 0 10 When applied for,

Special 3/5 fee ... £ 25 : 18 0 20 JUL 1939

Donkey Boiler Fee ... £ : : When received,

Travelling Expenses (if any) £ : : 75. 7 1939 11/8

Committee's Minute

Assigned

FRI 19 APR 1940

See HKG J.C. 8541

R. M. J. Pitt

Engineer Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation