

# REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

DISCLOSED SECTION No. 785

Date of writing Report 11-7-1962. When handed in at Local Office 1962. Port of MONTREAL

No. in Book 30001 Survey held at Quebec "CAP SAUMON" Date of First Survey 2-4-62. Last Survey 17-4-1962. (No. of Visits 2)

on the Steel M.V. "SAUIT-au-MOUTON" M/M. 13410 By whom G. T. Davie & Sons Ltd. When 1945 - 7

TONNAGE:— Built at Lauzon Owners Quebec Paper Sales & Transportation Co. Ltd. Managers

GROSS 450 NET 237 Surveyed Afloat or in Dry Dock? Afloat Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Last Report, No. 13924 Port MTL

REPAIRS, OR EXAMINATION AS PER RULE FOR LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
*100A1 River St. Lawrence service to Anticosti Island	*LMC.CS. 8,58
Docking 8,58	TS(CL) P. 4,59N
Lake s.s. 8,58	ST. 4,59
A.S. 4,61	Oil Engs.

YES NOW Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

ITEMS EXAMINED AND CONDITION FOUND, ETC.	
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	Good
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	Good
Under Engines <del>Scrubbed</del>	Good
Masts, Rigging & Outfit.	-
Windlass & Hawse Pipes.	Good
Air & Sounding Pipes with closing appliances.	Good
Pumps and Pumping arrangements outside machinery space.	Good
Steering arrangements including gear.	Good
W.T. Doors & Sluice valves.	-
Ventilator coamings with their closing appliances.	Good
Hatchway coamings with their closing appliances.	Good
Casings, companionways and their closing appliances.	Good
Superstructure bulkheads with their closing appliances.	-
Guard rails & freeing ports.	Good
Overboard discharges, also ash chutes & other shell openings.	Good

DISCLOSED SECTION No. 785B

	EXAMINED	TESTED	CONDITION
Peaks	F. & Aft	Yes	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line <del>Survey</del> Survey been held?	Yes		
Has a Grain Survey been held?	No		
Has a Damage Survey been held?	No		

### General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, 1,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,62.

(The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Survey Fee \$ 30.00 Special Damage or Repair Fee (if any) \$ Travelling Expenses \$ 5.00 Second Surveyor's Fee (if any) \$ Fees applied for, July 17th 62 QBC-94

S. P. Wilson P. S. H. ... Surveyor to Lloyd's Register of Shipping.

Committee's Minute THURSDAY 16 AUG 1962 Character Assigned AS 4-62

(D. HALKETT) WEDNESDAY 21 AUG 1963

Noted for Header

NOTED FOR POSTING "Laid up pending Survey" Lloyd's Register Foundation

013409-013416-0071

ITEMS EXAMINED AND CONDITION FOUND, ETC.			
IN DRYDOCK Outside shell, Sternframe & Rudder			
Bunkers - coal			
Striking plates			
Chain locker & Cable holdfasts			
Equipment letter			
Anchors, No. of			
Cables (State if now ranged)			
Length on board		Fathoms	Mean diameter.
Rule length		Fathoms	Diameter,

It should be stated whether it was considered necessary to test any tanks at this time.

TANKS	EXAMINED	TESTED	CONDITION
O.F. Tanks.			
Double bottom tanks.			
Feed water & F.W. tanks.			

Undocking Date.....

Was it considered necessary to drill the plating at this time? .....

General Notes on Survey, not included above.....

**WEAR & TEAR REPAIRS:-**

20 wood hatch covers renewed. 1 tarpaulin renewed.

Hold ceiling part renewed.

Minor voyage repairs.

**S.R.I. APPENDIX:-**

Bottom to be examined annually (cement omitted)

**NOW DONE:-**

Hold ceiling lifted and bottom internally cleaned, examined and coated, found in good condition.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:-

ANCHORS.

Number of Certificate.	Anchors.	WEIGHT EX. STOCK.		WEIGHT OF STOCK.		TEST PER CERTIFICATE.		WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Surveyor.
		lb.		lb.		lb.		lb.				

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per rule.		Description.	Makers of Cables.	Where and when tested and Surveyor.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			

Stream Chain }  
or Wire }



© 2021

Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.