

"
M.S. Koolinda.....

---- oOo ----

IT IS SUBMITTED the OWNERS..... Surveyors
be informed in reply to their letter of 2ND APRIL 1958.....
that according to the records in this Office the following
remains to complete the Continuous Survey cycle of the
machinery at this date. It should be borne in mind that
delay in completing the Survey may involve the examination
of additional items.

Examine:-

*Pumping arrangements.
Steering Gear and Windlass.
Electrical Installation.*

*The vessel's class is at present subject to the Port main Engine Exhaust
manifold inner casing second length from forward temporarily repaired
being dealt with as found necessary by the Special Survey.*

*Atty. R.
9.4.58.*



© 2021

Lloyd's Register
Foundation

013409-013416-0269