

3m.12,32.

The class is subject to main boiler safety valves being adjusted; and to the donkey boiler not being used again.

5 E
-3 MAY 1934

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Heath Abbey

Rpt.

Levs.

No. 20259.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

~~DAMAGE & WEAR AND TEAR.~~

main boiler safety valves adjusted.

It is submitted the vessel is eligible to remain as classed without fresh record of Survey ~~as recommended.~~

Subject to the
DONKEY BOILER
not being used again.



© 2021

Lloyd's Register
Foundation

013436-013443-0046