

... should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Dr).

"BALDUR" - Rjk. Rpt.No.3018.

IT IS SUBMITTED, before this case receives the consideration of the Committee, and as it is not clear from the report that all the items of the Restoration Special Survey have been dealt with -

- (1) the attached extract from the Wood Rules should be sent to the Surveyor for his information and retention, and he be requested to confirm that all the requirements of the Restoration Special Survey have been complied with, and
- (2) he also be requested to furnish the qualifications and experience, including practical experience, of the Wood Expert who has assisted in the survey of this ship as Mr. Peter Ottason is not an approved expert in wood construction.

ABM

20.6.58.

blsg th - Rjk



© 2021

Lloyd's Register Foundation

013463-013470-0204
013463-013470-0206