

RECEIVED

4 DEC 1946

Cloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 3rd December, 1946.

reference Dear Sir, ANSD.....

In reply to the classing letter of the 29th November, having reference to our report No. 53793 on the "GREBBESTROOM", we beg to inform you that seven $\frac{3}{4}$ " diameter rivets are fitted in the seams of the shell plating between the frames amidships excluding rivets in the frames and not six as inadvertently stated on the report.

All the main frames from frame 88 to 100 inclusive are continuous to the shelter deck and a double channel pillar 6" x 3" x 3" x .36" is fitted in the 'tween decks on frame 73.

The depth of the margin plate amidships is 29" excluding the flange.

We are, Dear Sir,
Yours faithfully,
The Surveyors,

Per:-

Cloyd's Register
Foundation

The Secretary,
LONDON.

013588 - 013595 - 009

Referred to Mr. Parry

to.

For Ship Surveyors

1111
2

As per Deck Bill
The above is a copy of the bill
for the surveyors (E. E. Rats.) to be
made.

The bill is for 100 including
the surveyors and not for the
surveyors as the bill is for the
surveyors to be made.

Ocean Chamber, 10, Abchurch Lane, London, E.C. 4

1111



© 2021

Lloyd's Register Foundation