

COPY

## LLOYD'S REGISTER OF SHIPPING



No. C-9254

Port Nagasaki

23rd August, 1961

LOADING CERTIFICATE FOR CLASSED REFRIGERATED  
CARGO INSTALLATION

The temperatures in the chambers were noted to be as follows:

NAME OF SHIP m.v. "MANHATTAN MARU", 9556 tons gross of Kobe.

**This is to Certify** that I have examined the Refrigerated Cargo Installation of the above named ship as stated below for a Loading Port Survey as required by the Society's Rules.

The installation is classed with the Society and has the survey record of LLOYD'S RMC in the latest Supplement to the Register Book available at this Port. A certificate on board dated 23rd Aug., 1961 issued at the Port of Nagasaki states that a later record of LLOYD'S RMC 8/61 has been recommended.

The chambers specified overleaf and their equipment, together with the refrigerating plant under working conditions, have been examined by me in accordance with the requirements of the above-mentioned Rules, and in my opinion, are in a fit and efficient condition.

I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me have been completed to my satisfaction.

Before loading was commenced, the temperature of the cargo chambers was reduced as shown overleaf.

Surveyor to Lloyd's Register of Shipping.

A. IMAZUMI

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



COPY

The following chambers have been examined:

LLOYD

No. 3 hold upper tween deck space.

Port forward chamber

Port after chamber

Starboard forward chamber

Starboard after chambers



LOADING CERTIFICATE FOR CLASSED REFRIGERATED  
CARGO INSTALLATION

The temperatures in the chambers were noted to be as follows:—

No. 3 hold upper tween deck space.

Port forward chamber - 23°C

Port after chamber - 22°C

Starboard forward chamber - 22°C

Starboard after chamber - 22°C

The installation is classed with the Society and has the survey  
recorded in the latest Supplement to the  
Register Book available at this Port. A certificate on board  
dated 23rd Aug. 1921 issued at the Port of  
that a later record of LLOYD'S R.M.C. has been recommended.  
The chambers specified overhead and their equipment, together  
with the refrigerating plant under working conditions, have been  
examined by me in accordance with the requirements of the above-  
mentioned Rules, and in my opinion, are in a fit and efficient condition.  
I have transmitted to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me have been completed to my satisfaction.  
Before loading was commenced, the temperature of the cargo  
chambers was reduced as shown overhead.

Surveyor to Lloyd's Register of Shipping.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:  
"While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly  
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
liable to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021

Lloyd's Register  
Foundation

Survey Fee

Travelling exp