



Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

(P. O. Box No. 446)

83, KYO-MACHI,
IKUTA-KU

RECEIVED

24 AUG 1953

Kobe, 18th August, 1953.

Reference

Dear Sir,

Ans'd
Class Cont. 13.7
FE.
T.S.M.V. "NEW-YORK MARU"

Nagoya S.B.Co., Ltd., Yard No. 104

Tamashima Engines No. 237 & 238

In reply to your letter dated the 31st July 1953 regarding the above engines, we have to report that the date of Approval of the torsional vibration characteristics which was reported on the first entry report 4b. are not the 2nd and 20th December 1952, but it is the 15th September 1952 for the sister ship "YOKOHAMA MARU (Nagoya Yard No. 103) as pointed out by your letter. *KOB 10.8. In 22. CL 25*

It is confirmed that a notice board has been fitted at the conral station stating that "The engine is not to be operated continuously below 35 R.P.M." and the engine tachometer is marked accordingly.

Regretting that this mistake was allowed on our report.

Yours faithfully,

H. Ramakrishna
For the Surveyors.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

013596-013603-0169

CLASSIFICATION

H.
Eng.

[Handwritten signature]

FOR THE ONTARIO 27.8.52

IDENTIFICATION

3. Forget two no bowolls saw oketain and that gubbtorged

is a common occurrence at the
of the only one that has been lifted
of the only one that has been lifted
of the only one that has been lifted

of the only one that has been lifted
of the only one that has been lifted
of the only one that has been lifted
of the only one that has been lifted

OF THE ONLY ONE THAT HAS BEEN LIFTED
OF THE ONLY ONE THAT HAS BEEN LIFTED
OF THE ONLY ONE THAT HAS BEEN LIFTED

OF THE ONLY ONE THAT HAS BEEN LIFTED

RECEIVED

RECEIVED
RECEIVED
RECEIVED

RECEIVED WITH THE BRITISH CORPORATION REGISTER



© 2021

Lloyd's Register
Foundation

HIPS NZ

created by CH