

Rpt. 8(L)

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Received London

29 JUN 1964

Ship's Name SS/MS "JOHN ERICSSON"

Gross tons 3650

Is there a rpt. 9? Yes

Port Toronto, Ontario

Rpt. No. 4941

No. of visits One (1)

First date and Last date

1-4-64

Interim Cert. issued & copy herewith? -

Damage rpt. issued & copy herewith? -

Last rpt. (H.Q. only) T/O 4878

Date of completing rpt. 1-4-64

Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat

Last date of examination in D.D. -

Has a Load Line Survey been held? Yes

Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (DR); (EQ); (Rig)

Survey fees \$36.00 U.S.S.A. \$ 4.00

Damage fee -

Expenses \$5.00

R.F.B. Tto-2336, June 8, 1964

S.A. fee -

I/we have surveyed the above ship in accordance with the Rules for Lake ANNUAL Survey

Examined & Condition

Examined & Condition

Holds, incl. blkhds., inner btm. plating, etc

Good

Pumps & pumping arrgts. outside mchy. space

Good

Bilges & ceiling

Good

Steering arrgts. incl. gear

Good

'Tween decks

-

W.T. doors & sluice valves

-

Deck & deck erections

Good

*Ventilators

Good

Machinery space

Good

*Hatchways

Good

Under E. & B.

Good

*Casings & companionways

Good

Masts, rigging & outfit

Good

*Superstructures

(None)

Windlass & hawse pipes

Good

Guard rails & freeing ports

Good

*Air & sounding pipes

Good

Overboard discharges, ash chutes & other shell openings

Good

Examined & condition

Tested & condition

Examined & condition

Tested & condition

Peaks Good

-

Tankers { Cargo tanks, Cofferdams, Pump rooms

Side tanks in hold

Deep tanks

Has a grain survey been held? Yes

Has a damage survey been held? No

The items now surveyed are detailed on this report. All were found or placed in good order unless otherwise stated.

I/we recommend that this ship remain as classed with fresh record of Annual Survey. 4/64.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

T.L. Millar (T.L. Millar) Surveyor(s) to Lloyd's Register of Shipping

Date of Committee

TUESDAY - 7 JUL 1964

Minute

AS 4.64, RBS 4.64

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation

should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the date

013611-013617-0008

*These items to include their closing appliances