

Rpt. 8.

B.C. CLASS.

(Received at London Office

AUG 1950)

No. 17910

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 10th August 50

When handed in at Local Office 10th August 50

Port of BRISTOL

No. in Survey held at Bristol & Avonmouth

Date, First Survey 7th July

Last Survey 9th August,

19 50

Reg. Book.

(No. of Visits 2)

58766

on the ~~Wentworth~~ Steel s.s. "ERNEST BROWN"

TONNAGE:—

GROSS 54

UNDER DK 53

NET

Built at Thorne, Doncaster

By whom R. Dunston Ltd.

When 1944

MONTH. 9

Owners T. R. Brown & Sons Ltd.

Owners' Address

(If not already recorded in Appendix to Register Book).

Managers

Port belonging to

Hull

Surveyed Afloat or in Dry Dock?

Afloat

Name of Dock Bristol & Avonmouth

Destined Voyage

Cell D Bor D Ba

feet; uE & B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. B.C. Summary Port

Rpt No 691

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. no damage

Was a damage report made by anyone else? if so, by whom? no

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Cert. B issued, copy attached.

Now Done.

Annual Survey: Weather decks, casings, coamings, closing appliances, ventilators, air pipes, windlass, steering gear and general equipment examined and found in satisfactory condition.

SUMMARY OF DAMAGE REPAIRS:—

Renewed

Removed and Fitted or Repaired

Fitted or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors and Bracket Floors

Beams.

Inner Bottom Plates.

Dk. Plates.

Other Items:—

PRESENT CONDITION OF THE

Decks satisfactory

Caulking of Decks do

Coamings do

Beams & Postings —

Outside Plating —

" " in way of side lights —

Frames pt. exd. Good

Reverse Frames —

Longitudinals —

Transverses —

Floors —

Kedgions —

Stringers —

Inner Bottom Plating —

Have the Tanks been examined internally? No

Have the Tanks been tested? No

Bulkheads part exd. Good

Ceiling —

Cement or Asphalt —

Rudder —

Steering gear and its connections Good

Windlass Good

Have pumps been examined and found efficient? —

Have Sluice Valves been examined and found efficient? —

Have Watertight Doors been examined and found efficient? —

Have Ventilators and their Coamings been examined and found efficient? Yes

Air and Sounding Pipes Good

Doubling Plates under Sounding Pipes —

Engine Room Skylights Good

Coal Bunkers, Openings, Covers, &c. —

Oil Bunkers —

Scuppers Good

Cargo Hatchways —

Hatches —

Planking —

Caulking —

Treenails —

Breasthooks & Stemson —

Transoms, Pointers & Crutches —

Timbers of Frame at openings —

" " at other places —

Stringers, Clamps & Shelves —

Salting —

State if examined.

Copper, or Y.M. —

(State if on Felt.)

When fitted, Month Year —

Boats —

Masts, Yards, &c. satisfactory

Condition, how ascertained from deck

(State if wedges removed)

Equipment letter C16

Anchors, No. of —

Cables (State if now ranged) No

" length mean diamr. —

(on board.)

" Rule length size —

Chain Locker —

Hawsers & Warps sufficient

Standing and Running Rigging efficient

Sails —

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, so far as now seen, is eligible in my opinion to remain as classed in the Register Book with fresh record of Annual Survey 8,50.

Survey Fee (see Section 29) Annual Survey 3: 0:0

Fees applied for,

Special Damage or Repair Fee (if any)

19

(see Sec. 29)

Received by me,

Traveling Expenses (if chargeable)

19

Second Survey Fee (if any)

Committee's Minute

FRI. 1 SEP 1950

Character Assigned

As 8.50

Ber. S 8.50

013618-013626-0065

Lloyd's Register Foundation

Is Certificate required? If so, to be sent to