

COPY

Ship's name "PETER LEIGH" Port Liv. No. 163394
Last survey date 9.1.64
GB Class is subject to set up bottom plating forward also wasted
after keel plate being specially examined and dealt
with as necessary next drydocking.

S.R.L. Appendix (as before or ~~none~~)x

Nature of present survey (afloat ~~and~~ in drydock)

Docking: Permanent repairs to H.W. damage:
Examination of S.R.L. and S.R.L. Appendix items.

Recommendation

NOTED

DS 1,64 Subject as above.

DS 1,64 Subject


IN S.R.L. APPENDIX.
(Bottom plating hogged)



© 2021

C.S.S. Records Dept.
to note.

Lloyd's Register
Foundation



013639-013642-0166