

EA

COPY

Ship's name "PETER LEIGH" Port BRE. No. 22426

Class is subject to Last survey date 4.10.63.

set up bottom plating forward being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: Temporary wear and tear repairs.
Permanent repairs to damage - causes not stated.

Recommendation SUBMITTED record of DS 10,63 be assigned, subject as above and to wasted after keel plate being specially examined and dealt with as necessary next drydocking.

DS 10,63 Subject

IN S.R.L. APPENDIX
Bottom plating hogged.

IT IS FURTHER SUBMITTED the Surveyors be advised that the ship was subject to "set up bottom plating fwd. being specially examined and dealt with as necessary next drydocking" and they be requested to advise whether the ship was examined and continues satisfactory and to do so in all future similar cases. (See note on back of report)

© 2021

Lloyd's Register
Foundation