


C O P Y
LLOYD'S REGISTER OF SHIPPING



No. B1-107547

Port Kobe

26th September, 1964.

This is to Certify that ~~we~~^{we} have surveyed part of the machinery of the m.s. "DAIKYO MARU" 13,224 Gross tons of Tokyo for advancement CSM, MBS and TS(CL) whilst the vessel lay afloat and in drydock at Aioi on the 26th August 1964 and subsequently

and that all ~~my~~^{our} recommendations have been carried out to ~~my~~^{our} satisfaction. ~~We~~^{We} are ~~is~~^{are} reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned CSM (with date) on completion, MBS 9,64 and TS(CL) 8,64, subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

H.P. turbine casing, rotor, blading, bearing, and thrust.
H.P. and L.P. turbine flexible coupling.
H.P. and L.P. reduction gearing.
Forward drain pump.
Main circulating pump.
Forward auxiliary condensate pump.
Sea water cooling pump for evaporator.
Starboard steering machinery.
Windlass.
Port main turbo generator engine complete.
Propeller and outside fastenings.
Sea connections.
Screwshaft.
Port and Starboard main boilers with superheaters.
Air heaters and economisers.

M. Kerr
Surveyors to Lloyd's Register of Shipping
N. Kerr, M. Kitan, J. Nonomura

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) EP above 150°F	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1 - 10,64 KOB

NK: sk

013639 - 013642 - 0194