

19th September, 1961.

BUENOS AIRES

32999, 3013, 17 - As recommended.

"GOYA" Before your First Entry report No. 32214 receives consideration of the Committee I shall be glad if you will give the date of approval of the cartridge type fuses now fitted, and also give the makers of the "Pami" cartridge fuses as there is no record of the approval of these fuses in this office.

Please state the method of initially charging the air receivers.

It is concluded that the draught now reported is incorrect (Refer Secretary's letter dated 19th October, 1960) but I shall be pleased to receive your further comments on this matter.



Lloyd's Register  
Foundation

013651-013655-0170