

RECEIVED

3 - MAR 1962

T  
COMMITTEE LDN

Ans'd.....

CABLE IN

Z196 CDD224 FAX NEW YORK 62 2 432P VIA WUCABLES

LT COMMITTEE

NDONEC3

ISLAND

PARADISE ISLE AT PRESENT UNDER SURVEY IN BAHAMAS  
REPRESENTATIVE OF BUILDERS AXXX HAS ADVISED ONXXX OWNERS THAT  
SHELL RIVETS SHOULD HAVE COUNTERSUNK HEADS AND BE  
INSERTED FROM OUTSIDE STOP AS THIS CONTRARY TO NORMAL  
PRACTICE AND STATED TO BE DIFFERENT TO THAT ADOPTED  
DURING CONSTRUCTION WHEN THE RIVETS INSERTED FROM  
INSIDE AND HAMMERED ON OUTSIDE PLEASE CABLE COMMENTS  
AND INSTRUCTIONS

NYMDIBLE.

SENT RD

VCOMMITTEE LDN



© 2021

Lloyd's Register  
Foundation

013656-013663-0199



REPORTS

*ml*

*up's Mini 27.1 Ave*

*Changase*



© 2021

Lloyd's Register  
Foundation