

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

13th July, 1965.

Dear Sirs,

C.
RLT/DET

CLASSING LETTER

8258 "CAMPERO". As recommended. The class of this ship is subject to the shell plate D.7 (port side) being specially examined and dealt with as necessary by the SS (not D.7 (starboard side) as inadvertently reported in the S.R.L.) and it is concluded that this item has been examined and found satisfactory, but your confirmation is desired.

Assignment of a new notation of SS 4.65 has been deferred pending completion of the ES. The electrical installation requires to be examined and the evaporator safety valves adjusted and as this is an ES case the following items last seen in October 1962 should also be examined:-

Independent main SW cooling pump
Condenser circulating pump

The SPS should have been held at this time as now due and the Owners should be asked what arrangements are being made for this survey to be held.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
BARCELONA.

© 2021

Lloyd's Register
Foundation

013671-013677-0015