

23 JUN 1965

Ship's name BALBUS

Port LGS

No. 4083

Class is subject to — NIL

Last survey date 15-9-64

Limit date 31/3/64

Docking Wear down 0.042"

TS due 1/66 now held

MBS due 3/64 now held

ES due 6/64 now commenced.

The Surveyor report The main engine L.P. cylinder found cracked in central web of the upper & lower steam ports and a doubler fitted over the C.I. cover flange as the crack was not accessible for repair. The recommendation note be made in the Appendix.

It is submitted that this vessel is eligible for THE RECORD. TS (024) 4/64 } now and  
MBS 7/64 }

Record ES 9/64 when the Survey has been completed by examination of Pumping arrangements and 1/2 tested working and manoeuvring

*LD*  
23/6/65

In a letter the 16/4/65 the Owners requested the vessel be taken out of Class on the Class was withdrawn by the Committee 7/5/65