

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS/MS~~ "BALBUS" *Class Withdrawn. O.R.*

Gross tons 296 Port of Registry ~~Lagos~~ Port Lagos

Date of build 8/46 Is there a Rpt. 9? Yes Rpt. No. 4083

No. of visits 14 First date 31. 3. 64 Last date 15. 9. 64.

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) *HE 2541*

Date of completing rpt. 30. 4. 65. Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Afloat & D.D. Last date of examination in D.D. 17. 8. 64

Has a Load Line Survey been held? No Summer freeboard as verified

NO JUN 1965

State which additional Rpt. 8 is attached: (~~Cont~~); (PS); (~~DE~~); (~~DR~~); (~~DR~~)

Survey fees	Damage fee	Expenses (Cables)
Docking £14 - 0 - 0.		£12 - 14 - 0.
S.S. £124 - 0 - 0.		S.A. fee <i>30</i>

We have surveyed the above-named ship in accordance with the Rules for Special Survey and Docking for Steel Ships.

Examined for Special Survey:

- Shell plating.
- Port & starboard inboard fuel bunkers.
- Port outboard fuel bunker.
- Port & starboard ballast tanks.
- Chain lockers.
- Transom space.
- Port feed tank.
- Starboard feed tank.
- E. R. bilges.
- Decks, superstructure, forward accommodation, masts and rigging.

Repairs Now Done:

- Plate A2 from for'd on starboard side renewed (wasted).
- No.1 plate on sheerstrake starboard side cropped and part renewed (indented).
- No.7 plate on sheerstrake starboard side cropped and part renewed (indented).
- Deck plating round starboard hawse pipe wasted. (cropped and part renewed).

P.T.O.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. We recommend, therefore, that this ship remain as classed with/without fresh record of dry docking 8/64 now and SS. 9/64 when the E.S. has been completed, subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee **FRIDAY 25 JUN 1965**  
Minute *noted*

*(See 6th minute dated 7.5.65)*

*G. V. Peace*  
R. S. Crowther & H. Pollock,  
Surveyors to Lloyd's Register of Shipping

ALSO FOR
SPE FOR
NOTED BY
C.S.S.
TRO
DEPT
SRL
POSTING
HEADER
CERT

Lloyd's Register Foundation

FOR CHAIRMAN CLASSN. CTTEE

013750-013759-0192 1/2

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

S.R.L. "Stem bar set over to be specially examined at No.234 next drydocking."

Nothing done this time.

Ref: This office letter 21/4/65, Secretary's cable dated 30/4/65 and this office cable dated 2/5/65.

"Owners desire class to be withdrawn".  
Vessel to be sold.

**PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.** The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations to existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2021

Lloyd's Register  
Foundation

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~SS/MXX~~

"BALBUS"

S.S. ( ) Due

Port **Lagos**

Rpt. No. **4083**

<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>	
In dry dock from	31 - 3 - 64	* Air & sounding pipes	Good
" " " to	14 - 4 - 64	Doublers under " "	Yes
Shell plating	Good	Steering arrangements (main)	Good
Sternframe	Good	" " (aux)	
Rudder	Good	Windlass	Good
Was rudder lifted?	No	Masts & rigging	Good
Plating, etc. in way of shell openings	Good	Hand pumps & suctions	-
Side scuttles & deadlights	Good	W.T. doors	-
Overbd. scuppers & discharges	Good	Bulwarks, freeing ports, etc.	Good
F.P. spaces	-	Summer freeboard as verified	-
Chain locker	Good		
A.P. spaces	-		
Transom Space	Good		
Engine space	Good		
Boiler space	Good		
Under E. & B.	Good		
Coal bunker	-		
Tunnel & well	-		
Cement, asphalt, etc., on btm. shell	-		
Weather decks	Good		
* Casings	Good		
* Deckhouses	Good		
* Superstructures	Good		
* Skylights	Good		
* Companionways	Good		
* Hatchways	Good		
* Ventilators	Good		
Other items:			

EQUIPMENT:

Not examined

Equipment letter

Fee ltr., if diff. from eqpt. ltr.

Anchors: No. on board

Cables { State if ranged  
Length on board  
Mean dias. range from to  
Rule length Dia.

Mooring ropes

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

*G. K. Peace for R. & A. Rowley*  
R. S. Crowther for H. Pollock  
Surveyor to Lloyd's Register of Shipping  
H. Pollock  
Foundation

0192 2/2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		P & S O.F. bunkers (inboard)	23/6/64 Good	S.S.
"	'Tween decks		Port outboard	14/8/64 Good	SS
			Settling tanks		
No. 4	Hold				
"	'Tween decks		<del>Deck</del> tanks		
No. 5	Hold				
"	'Tween decks		P & S <del>Stb</del> tanks Ballast	30/4/64 Good	S.S.
No. 6	Hold		Wing tanks		
"	'Tween decks				
			Other tanks:		
			Chain Locker	7/4/64 Good	S.S.
			Transom space	7/4/64	9/4/64 (Good) S.S.
	Cargo battens		Port feed tank	10/4/64 (Good)	15/4/64 (Good) S.S.
	Ceiling, etc.		Stb. feed tank	30/4/64 (Good)	15/4/64 S.S.
			E.R. Bilges	13/8/64 (Good)	S.S.



© 2021

Lloyd's Register  
Foundation