

Ship's Name ~~SS/XX~~ "MUSWELL HILL" Gross tons 7131
 Is there a rpt. 9? Yes Port RANGOON Rpt. No. 06349
 No. of visits 2 First date 5-1-63 Last date 6.1.63
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? - Last rpt. (H.Q. only) - 3487. Png
 Date of completing rpt. 7.1.63 Surveyed at, if different from Port above -
 Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -
 Has a Load Line Survey been held? Part survey completed Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) (PS)

Survey fees K.240/- Damage fee - - Expenses K.20/-

S.A. fee K.100/-

I have surveyed the above ship in accordance with the Rules for General Examination for postponement of Special Survey in accordance with Circular No.1959.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend that this ship remain as classed ~~with without fresh record of dry docking~~ and that Special Survey be postponed until end March 1963.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

TUESDAY 19 FEB 1963

Minute

Deferred for SS. Surveyed (h+m)

Postponement of SS until 3.63 approved.

013850 - 013858 - 0021 1/2

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

4491.1.63 Note RAN (h+m) Postponement of SS until 3.63 approved.

118 JAN 1963

Approved

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/SS "MUSWELL HILL"

S.S. () Due

Port RANGOON

Rpt. No. 06349

<u>Examined & condition</u>	<u>Examined & condition</u>
In dry dock from	* Air & sounding pipes
„ „ „ to	Doublers under „ „
Shell plating	Steering arrangements (main)
Sternframe	„ „ (aux)
Rudder	Windlass X
Was rudder lifted?	Masts & rigging
Plating, etc. in way of shell openings	Hand pumps & suction
Side scuttles & deadlights	W.T. doors
Overbd. scuppers & discharges	Bulwarks, freeing ports, etc. good
F.P. spaces	Summer freeboard as verified 10' 6½" ✓
Chain locker	
*A.P. spaces	
Engine space	
Boiler space	<u>EQUIPMENT:</u>
Under E. & B.	Equipment letter
Coal bunker X	Fee ltr., if diff. from eqpt. ltr.
Tunnel & well	Anchors: No. on board
Cement, asphalt, etc., on btm. shell	State if ranged
Weather decks good	Length on board
* Casings good	Mean dias. range from to
* Deckhouses good	Rule length Dia.
* Superstructures good	Mooring ropes
* Skylights good	
* Companionways good	
* Hatchways good	
* Ventilators good	
Other items:	

* These items to include their closing appliances
Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021 *[Signature]*

Lloyd's Register
Surveyor to Lloyd's Register of Shipping
Foundation

0021 2/2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	good	F.P. tank		
"	'Tween decks	good	A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold	good			
"	'Tween decks	good			
No. 3	Hold	good	O.F. bunkers		
"	'Tween decks	good			
"3A	Hold	good			
"	Tween deck	good	Settling tanks		
No. 4	Hold	good			
"	'Tween decks	good	Deep tanks		
No. 5	Hold	good			
"	'Tween decks	good	Side tanks		
No. 6	Hold	-	Wing tanks		
"	'Tween decks	-			
			Other tanks:		
	Cargo battens	good			
	Ceiling, etc.	Fair			



© 2021

Lloyd's Register
Foundation