

013850 - 013858 - 0024

COPY

Ship's name *SS. MUSWELL HILL*

Port

*Penang (9A) # 3482.  
24/12/62  
Rangoon (9A) No. 6349  
& letter of 11/8/63.*

Class is subject to

*None.*Last survey date *6/1/63.*

*E.S. (due 12/61) (P.P. until 12/62 approved. 29/3/62 & further postponement until 3/63 approved 4/12/62, provided A.E. held).  
G.E. not held.*

*Insulation resistance of all electrical circuits found to be low (10,000/15,000 Ohms) at Penang and the Surveyor recommends that the forward stores and holds electrical circuits be disconnected. ~~at Penang~~. The Rangoon Surveyor makes no mention of the electrical installation in his report and it is not recommended that the electrical installation be repaired by 3/63, the electrical circuits to the cargo holds and forward stores to be disconnected meantime.*

S.R.L. - Appendix Note

C.S. Advanced.

*It is submitted that this vessel is eligible to remain as CLASSED.*

*subject as not recommended  
It is further submitted that postponement of E.S. until 3/63 meets approval.*

*It is concluded that the Rangoon Surveyor should go forward to Penang towards the Penang Surveyor's recommendations that the electrical circuits be disconnected from holds and forward stores be repaired at Rangoon.*