

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Motorship "MOANA ROA"
Official Number - Port of Registry Auckland
Owners New Zealand Government (Department of Island Territories)
Builders, and where and when built Grangemouth Dockyard Co. Ltd., Grangemouth, July, 1960

REGISTERED TONNAGES		MOULDED DIMENSIONS	
Gross	2892.57	Length	270' 0"
Net	1318.35.	Breadth	46' 0"
		Depth	22' 0"


This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 11th July, 1960 in a fit and efficient condition and in accordance with the Rules; also that she has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character 

subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	4 feet 8 inches (T).	Winter	5 feet 6½ inches (WNA).
Summer	5 feet 0¼ inches (S).	North Atlantic	
Winter	5 feet 4½ inches (W).	Allowance for fresh water for all freeboards	4¼ inches

Witness my hand,


Secretary.



Chairman.

71, Fenchurch Street, London, E.C.3. 22nd September, 1960.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”



© 2021

Lloyd's Register
Foundation