

TELEPHONE No. 3230

3230

TELEGRAMS: ~~Lloyd's Register, Dartmouth.~~

Lloydreg Torquay.

Lloyd's Register of Shipping,

6 Beacon Quay, ~~25, Victoria Road,~~

TORQUAY. Dartmouth, 3rd September, 1947.

Dear Sir,

"PHYLLISIA"

In reply to your letter of the 19th ultimo, regarding my report No. 7810. I enclose herewith a plan showing the steelwork in way of the feed water tank together with a plan of the pumping arrangements. These latter are as originally fitted excepting that an additional suction has been fitted in the fore end of the hold, and this complys with the Rules. The new forecastle has been built equivalent to the requirements of the Rules for steel trawlers and plan is forwarded herewith. The only water ballast tank fitted is the new feed water tank amidships. The Fore and After peak tanks although only dry were filled and tested under survey. The structure of the bunker tunnel still exists but has been pierced in several places and the watertight door still remains at the stokehold end, but since the connection to the reserve bunker has been blocked by the new feed tank in the main bunker it is no longer necessary.

The bulkhead at frame 65 is a wooden one and has previously been shifted aft from frame 67. There are no other major structural alterations.

Yours faithfully,

The Secretary,
LONDON.

013890 - 013899 - 0319

Referred to the Chief Ship Surveyor

RJ

Also for Mr. Stadden to note.

Jerris

Noted LM 17/9/47



© 2021

Lloyd's Register
Foundation