

"PHYLLISIA"

Torquay

No. 7810

It is submitted before this case receives consideration the Surveyor be requested to forward a plan of steelwork in way of the feed water tank now built into this trawler, including particulars of riveting etc., also plan of Pumping.

He should also state if the new forecastle has been built to the requirements of Section 17 of the Rules for Steel Trawlers, and give positions and capacities of all the water ballast tanks examined and tested by him, as no records of these are in this Office - except of course the F.W. tank now reported.

He should also be requested to state if the bunker tunnel still exists and has a W.T. door in the boiler room forward bulkhead.

From comparison with the original plan of the approved Profile & Decks and the General Arrangement now submitted, it would appear (1) that the bulkhead on frame 67 has been shifted aft to frame 65, and (2) the reserve bunker has been dispensed with and this space added to the fish-hold.

The Surveyor should also advise any other major structural alterations.



© 2021 16.8.47

Lloyd's Register
Foundation

013890 - 013899 - 0320