

Ship's name

"PORT JACKSON"

Port

LIV

No. 165105

Class is subject to

Last survey date 29.10.6

Starboard aft outboard main engine air compressor L.P.  
piston (cracked now repaired by welding 8.64) being  
specially examined by 1.65.


CSM Advanced.

DBS due 11.64 now partly held.

IT IS SUBMITTED that this vessel is eligible to remain  
as classed, with fresh record of DBS 10.64 on completion of  
the Survey, subject as above.

TO COMPLETE DBS.

Safety valves of the upper boiler to adjust under steam.



© 2021  
24.11.64.

Lloyd's Register  
Foundation