

COPY

Ship's name *Port Jackson*

Port

No.

Class is subject to

Last survey date

*at Rotterdam - Remains of side bottom  
and bolts examined & crack  
detected & 50% (uq) found fractured.  
All bolts both fractured & those  
found without defects now  
renewed & bedding of boltheads to  
lower halves of bearings checked &  
corrected where necessary & Surveyor  
recommends that the condition imposed  
by Antwerp Surveyors be deleted*

*machinery damage - Lisbon, — P.M.P. scavenge pump  
crosshead slipper guide shoe detached & had  
fallen into crankcase - Sc.pp. piston rod bent.  
Guide shoe now renewed & Sc.pp. piston rod  
straightened.*

*It is submitted that  
this vessel is eligible to  
remain as CLASSED*



©2021

*subject as above now amended*  
Lloyd's Register  
Foundation