

29 DEC 1964

Ship's Name SS/MS "PORT JACKSON".

L.R. 528240

Gross tons 9827

Port of

Registry

LONDON.

Port FALMOUTH.

Date of build 1, 1937

Is there a rpt. 8? Yes.

Rpt. No. 14689

No. of visits One.

First date 29.11.64.

Last date

Interim Cert. issued
& copy herewith?

Yes.

Damage rpt. issued
& copy herewith?

No.

Last rpt. (H.Q. only)

Date of
completing rpt.

18.12.64.

Surveyed at, if different from Port above

Is a rpt. 9A
attached?

No.

MN

2040

Nature of survey

Docking.

Survey fees

Damage fee

Expenses

S.A. fee

DOCKING

Propellers Good. 9

Sea connections Not examined. Oil gland

None.

Fastenings Good.

Wear down of stern bush
(if relined, state clearance
before and after)

P .125"

S .050"

Has screw/tube
shaft been drawn?

No.

Date of examn.

Has shaft been
changed?

-

Has shaft now fitted been previously used?

-

Has shaft now examined/fitted a continuous liner?

-

Approved oil gland?

-

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS

(State if oil fired—OF
or exhaust gas—EG)

MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors
and fasteningsSafety valves { Sat
adjusted to { SptBoiler securing
arrangements

Main economisers

Steam heated
steam generatorsForced
circulating pumpsHave saturated steam pipes in cylindrical boiler
smoke boxes been examined as required by the Rules?Exhaust gas heated economisers
and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system &
remote controls examined
in accordance with rules ?

I recommend that the machinery of this ship remain as classed with/without fresh record of survey subject to all outstanding conditions of Class attached thereto being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

Surveyor to Lloyd's Register of Shipping

MONDAY 15 MAR 1965

See MEX 22481

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		l Generators & governors	
b Exciters			
c Air coolers		m Motors	
d Motors			
e Air coolers		n Switchboards & fittings	
f Control gear cables, etc.		o Circuit breakers	
g Insulation resistance		p Cables	
h Insulating oil test		q Insulation resistance	
i Overspeed governors		r Steering gear generators & motors	
j Magnetic couplings		s Navigation light indicators	
k Air gap			

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

CONDITIONS OF CLASS.

Nothing done at this time.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.