

Copy of letter dated 24.11.65. Received from Nippon Yusen Kaisha, Tokyo
Attached to Yokohama memo 27.11.65. Relating to "SAIKYO MARU".

COCHRAN BOILER RIVETTED SEAM

4 to 12

Your letter dated 6th October, 1965 concerning the above
subject duly to hand.

However, we should say as impracticable if the above work
to be done at the time of boiler survey. So we request you that
the test holes should not be drilled on boiler lap-riveted longitudinal
seams of our vessels including "SAIKYO MARU".

We believe that the above arrangement will meet with your
approval.



© 2021

Lloyd's Register
Foundation

013997-014203-0064

8/R