

CARIBIA

Tri 2.66 Repair to electrical installation fire damage.

Subject to :-

1) Unlabeled generator set N.T.B.U.
(Centre)
with approved plates.

2) Elec. installation to exist
by 5.66 (not done before
after being ^{recess failed} laid up.)

Rep 8.66 } Repair to port generator,
Rot 9.66 } has further damage due to
flooding temporarily
dealt with.

Subject to :-

3) Load paralleling & megger
tests to be c/o on port generator
in main E.H. by 10.66

Son 10.66

Subject limit (3) extended to 12.66

(X)

Tri 26.10.66

Deletion of Subject (2) recommended
because of six months service
since recommendation, but
H.Q. extended limit to 12.66

Gen 3.67

all Subjects (1)(2)(3) dealt with.

~~but no opportunity to witness load~~
~~paralleling & governing~~
tests on A.C. generating sets
recommended to be done
by 5.67

Nov 6.67

Unsuccessful attempts made
to load parallel etc. This vessel
left without repairs & has
recommended CLASS extension

Nov 11 4.7.67

2 mths extension requested
pending receipt spares.

15/7 Install at risk
- but -

Agreed but must
by end Sept.



© 2021

Lloyd's Register
Foundation