

X  
"PRINCE SALVOR"

Rpt. Hul. No. 52171

The Surveyors should be referred to their letter of the 26th ultimo and informed that the general arrangement plan on which the bulkheads are shown in red is incomplete as the recesses in the port and starboard wings above the lower deck between frames 51 and 47, forming part of the water and oiltight bulkhead at the forward end of the boiler space, have not been indicated thereon, thus causing inconvenience and delay.



© 2021

J.C.D.  
5.11.43

Lloyd's Register

Foundation

014023-014021-0132