

10, 40.

1E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME *Prince Salvador*

Rpt. *Rec. No. 52171*
Rec. No. 101239
Rec. " 33588"

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion



If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
approved type

Yes
No (2 liners)

The electrical equipment has been fitted under Admiralty survey.

This vessel's machinery appears to have been built in accordance with the Rules and the *Admiralty Specification* approved plans, and it is submitted she is eligible to be classed *+LMC 9.43.*

Fitted for oil fuel 9.43, F.P. above 150°F.

Insert in SRL:- Auxiliary steam pipes (Bessons steel) to be examined after four years service.

Stals Job



© 2021

19/10/43.

Lloyd's Register
Foundation

014023-014031-0144