

0134<sup>2</sup>/<sub>2</sub>

© 2021

See new certificate re new.  
T.V. endorsement.  
vessel now named Scandius  
& on the 9/11/51 Cert Copy of hull issued under TJEPOE



# Lloyd's Register of Shipping.

FOUNDED 1760.

RE-CONSTITUTED 1834.

United with  
THE  
BRITISH  
CORPORATION  
REGISTER

## CERTIFICATE FOR MACHINERY.

This is to Certify that the Machinery of the  
Steel Screw Motorship "Nordhern"  
British Swedish  
1042 1046 Tons, of Stockholm  
has been Specially Surveyed by the Surveyors to this Society during  
construction at Stockholm and was reported  
to be on the 20<sup>th</sup> July 1949 at Norrköping  
in good, efficient, and safe working condition.

The Record  $\times$  LMC 749 (Lloyd's Machinery Certificate)  
has been made in the Register Book, subject to Periodical Surveys  
as required by the Rules, and to the machinery spare gear being brought  
up to Rule requirements, and to a boiler blow-down cock being fitted to Rule  
requirements at the next dry docking

The Notation DB178 lb (Donkey Boiler) has also been made in the Register Book.  
Strengthened for Navigation in Ice.

### PARTICULARS OF ENGINES.

Description.	When Made.	Name and Address of Makers.	CYLINDERS.		Length of Stroke.
			No.	Dia.	
<u>Two stroke cycle</u> <u>single acting</u> <u>Oil Engine</u>	<u>1949</u>	<u>A/B Atlas Diesel</u> <u>Stockholm</u>	<u>5</u>	<u>13 <math>\frac{3}{8}</math>"</u>	<u>22 <math>\frac{1}{16}</math>"</u>

The engines must not be run continuously between 55 and 75 RPM and 120 and 140 RPM and the blower shafting to be examined after a period of service not exceeding twelve months

Witness my hand,


P. E. Clement  
Secretary.

R. A. A. A. A.  
Chairman.

71, Fenchurch Street, LONDON, E.C. 21<sup>st</sup> October 1949

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



2021  
Lloyd's Register  
Foundation