

Ship's name

n/v - DAGMAR -

Port

Sw. (9A)

No. 163 275.

Class is subject to

None

Last survey date *17/12/63.*

CGM advanced, Repairs

*P. M.E. No. 3 cyl. cover (crack) repaired by Mellock
& Sawyer recommends that the Port main engine No. 3
cylinder cover (Mellock 12/63) be examined by 6/64 (6 ms.).*

*St. M.E. No. 3 guide face found cracked at bottom edge
considered efficient but Sawyer recommends that the
Starboard main engine No. 3 guide face (crack) be specially
examined by 6/64 (6 ms.).*

what.

and, subject as recommended.



17/12/63 © 2021

Lloyd's Register
Foundation